

CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BOSSERT MANUFACTURING SITE CONTRACT NO.: 68-S6-2101
DELIVERY ORDER NO.: 2101-02-010 DATE: 09/30/97 T
SITE/SPILL NO.: S7 SHIFT: 8:00 - 4:30
EPA REGION: II OSC: Jack D. Harmon
CONTRACTOR: Earth Tech., Inc. RM: LeRoy Cassidey
MONITORS: START (McGarry)

DESCRIPTION OF WORK TO BE PERFORMED

- 1) Meet with OSC and discuss scope of work;
- 2) Conduct site walk and evaluate manpower/equipment/material requirements;
- 3) Arrange mobilization of additional manpower i.e., (3) Cleanup Techs and (1) Foreman;
- 4) Review technical reports and develop disposal strategy;
- 5) Arrange for Industrial Hygienist to visit site and to assist in the development of an health and safety plan;
- 6) Arrange for delivery of command post trailer and utility and telephone connections;

NUMBER OF PERSONNEL AUTHORIZED


1 -RESPONSE MANAGER 1-FIELD CLERK/TYPIST 0-CLEANUP TECHS.

EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED


ITEM	QUANT.	ITEM	QUANT.
PASSENGER CAR	1	RENTAL CAR	1

I CERTIFY THAT THE ABOVE WORK IS ORDERED AND AUTHORIZED BY THE CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED DELIVERY ORDER


SIGNATURE OF OSC



SIGNATURE OF CONTRACTOR'S REP.



426709



CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BOSSERT MANUFACTURING SITE	CONTRACT NO. 68-S6-2101
ORDER NO.: 2101-02-010	DATE: 09/30/97 T
SITE/SPILL NO.: S7	SHIFT: N/A
EPA REGION: II	OSC: Jack D. Harmon
CONTRACTOR: Earth Tech., Inc.	RM: LeRoy Cassidey
MONITORS: START (McGarry)	

DESCRIPTION OF EQUIPMENT REQUIRED

GENERAL VENDOR EQUIPMENT

EQUIPMENT

VENDOR SUPPLIES

SUBCONTRACTORS